

G-M WATER SUPPLY CORPORATION
PO BOX 727
HEMPHILL, TX 75948

Dear Customer,

This is to inform our customers that G-M WSC, PWS ID TX2020067, failed to meet the minimum treatment technique requirements for the month of September, 2016. Specifically our water system had more than 5% of the combined filter effluent turbidity readings above 0.3 NTU for the month of September. This occurred after a bleach valve failed to close after a cleaning process. As a result, there was too much bleach going into the clear well increasing our finished water turbidity. The valve was repaired and water was back to normal within 48 hours.

If you have any questions, please call Vance Hoyle at 409-787-2755.

Posted/Delivered on: December 20, 2016